

## **ATTENTION: Unique Installation Procedure**



This MP301-Type 1515 drum unit doesn't require developer initialization unless there are copy quality issues, and performing initialization may reduce the life of the unit. Before initializing:

- Shake unit back and forth 4-6 times
- Install the drum unit into the machine
- Power on the machine.
- Run test pages. Print the test pages rather than copy them.

If there are no print quality issues, the developer initialization is not necessary, and performing the initialization may reduce the life of the drum unit.

If test copies exhibit irregularities such as spots or backgrounding, follow the standard initialization process to ensure an appropriate and consistent mixture of toner and developer.



## **ATTENTION: Unique Installation Procedure**



This MP301-Type 1515 drum unit doesn't require developer initialization unless there are copy quality issues, and performing initialization may reduce the life of the unit. Before initializing:

- Shake unit back and forth 4-6 times
- Install the drum unit into the machine
- Power on the machine.
- Run test pages. Print the test pages rather than copy them.

If there are no print quality issues, the developer initialization is not necessary, and performing the initialization may reduce the life of the drum unit.

If test copies exhibit irregularities such as spots or backgrounding, follow the standard initialization process to ensure an appropriate and consistent mixture of toner and developer.



## **ATTENTION: Unique Installation Procedure**



This MP301-Type 1515 drum unit doesn't require developer initialization unless there are copy quality issues, and performing initialization may reduce the life of the unit. Before initializing:

- Shake unit back and forth 4-6 times
- Install the drum unit into the machine
- Power on the machine.
- Run test pages. Print the test pages rather than copy them.

If there are no print quality issues, the developer initialization is not necessary, and performing the initialization may reduce the life of the drum unit.

If test copies exhibit irregularities such as spots or backgrounding, follow the standard initialization process to ensure an appropriate and consistent mixture of toner and developer.



## **ATTENTION: Unique Installation Procedure**



This MP301-Type 1515 drum unit doesn't require developer initialization unless there are copy quality issues, and performing initialization may reduce the life of the unit. Before initializing:

- Shake unit back and forth 4-6 times
- Install the drum unit into the machine
- Power on the machine.
- Run test pages. Print the test pages rather than copy them.

If there are no print quality issues, the developer initialization is not necessary, and performing the initialization may reduce the life of the drum unit.

If test copies exhibit irregularities such as spots or backgrounding, follow the standard initialization process to ensure an appropriate and consistent mixture of toner and developer.